

•

CD NO.

**SECRET**

SECRET

50X1-HUM

ADVERTISE INDUSTRIAL SAFETY POSTERS -- Moscow, Trud, 5 Sep 50

The following list of the captions on industrial safety posters, offered for sale to Moscow Plants, may give some indication of the type of industrial accidents most troublesome to Soviet plant managers.

1. Don't undertake a new job without instruction in safety techniques.
2. Don't work without covering gears.
3. Don't work without covering drive belts.
4. Use a guide in putting on belts.
5. Use the right cutting tool.
6. Don't measure work while the machine tool is running.
7. Fasten work securely when operating a drilling machine.
8. Don't operate a drilling machine while wearing mittens.
9. Remove chips with a rake or brush.
10. Use safety ladder.
11. Don't block working areas.
12. Protect your eyes with shades or goggles.
13. Tie up your hair in a kerchief.
14. Use a portable safety light.
15. Be sure electrical equipment is grounded.
16. Be sure to ground electric motor housing.
17. Cover electric switches with insulating material.
18. Welders! Cover your work with shields.
19. Protect your eyes during welding.
20. Store oily rags in metal containers.
21. Carry cylinders or flasks in hand carts.
22. Carry acid bottles in hand carts.
23. Watch the level of water in the water gate.
24. Don't work without a shim-loosening knife.
25. Switch off the motor when a machine is unattended.

- 2 -

SECRET

**SECRET**

**SECRET**

SECRET

50X1-HUM

- 26. Enclose loose ends of bar stock.
- 27. Don't pass or stand under suspended objects.
- 28. Don't work with untested fastening devices.
- 29. Fasten loads securely.
- 30. Don't dry-sweep floors.

- E N D -

- 3 -

**SECRET**

SECRET